

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port Port of London. 12th March, 1932.

Huston & Hornsby Ltd., Engine No. 360560.
Type 1V3HZ.

C.16569.

1029/11/5118997.

D.2861.

This is to Certify that

T. D. Scott,

the undersigned Surveyor to this Society did at the request of

re. Huston & Hornsby Ltd., attend at their works for the purpose of
fining and testing one-one cylinder 4.3.0.3.A. Heavy Oil Engine No.
360560 manufactured by them to the order of Messrs. J. Charters, Ltd., and
used for auxiliary purposes on Lohmütz & Co. Ltd., Yard No. 1131.
Engine is direct coupled to one-3 K.W. electric generator No. C.165909
manufactured by Messrs. Laurence Scott & Electromotors Ltd.,

Particulars of the engine are as follows:-

Engine Number.....	360560
Type.....	1V3HZ
Number of Cylinders.....	1
Diameter of Cylinders.....	4.1/2"
Stroke.....	4.1/2"
Maximum Pressure.....	850 lb.
Brake Horse Power.....	7.1/2
Revolutions per Minute.....	1000
Span of Bearings.....	5.7/16"
Diameter of Journals.....	2.3/8"
Diameter of Crankpins.....	2.3/4"
Breadth of Webs.....	2.3/4"
Thickness of Webs.....	1.3/8"

This engine has been built under Special Survey, in
accordance with the Approved plans and Regulations of the Society, materials
workmanship being good.

On completion, the generating set was tried in the Shops
in working conditions, and the governors tried with satisfactory results.

For purposes of identification the cylinder block has
stamped thus:-

LLOYD'S TEST.
50 lb./sq.in.
TNS. 20.10.32.
Eng.No.360560.

T.D. Scott

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of
its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."