

18 DEC 1962

Ship's Name SS/MS "CITY OF CARLISLE" Gross tons

Is there a rpt. 8? Port LONDON. Rpt. No. 1148169

No. of visits First date Last date
Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. Surveyed at, if different from Port above

Is a rpt. 9A attached? YES. MN Nature of survey GEN. EXAM.

Survey fees Damage fee Expenses

S.A. fee

DOCKING
Propeller Sea connections Oil gland

Fastenings Wear down of stern bush

Has screw/tube shaft been drawn? Date of examn.

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to Sat Spt

Boiler securing arrangements

Main economisers

Exhaust gas heated economisers

Steam heated steam generators

Steam generator safety valves adjusted to

Forced circulating pumps

Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

G.A. MATTHEWS Surveyor to Lloyd's Register of Shipping

Date of Committee

MONDAY 17 DEC 1962

Minute

See Rpt. 9A.



Lloyd's Register Foundation

01800-01804-0235

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be omitted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?


Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
		525.	
a	Generators	l	Generators & governors
			GOOD.
b	Exciters		
c	Air coolers	m	Motors
			GOOD.
d	Motors		
e	Air coolers	n	Switchboards & fittings
			GOOD.
f	Control gear cables, etc.	o	Circuit breakers
			GOOD.
g	Insulation resistance	p	Cables
			GOOD.
h	Insulating oil test	q	Insulation resistance
			GOOD.
i	Overspeed governors	r	Steering gear generators & motors
j	Magnetic couplings	s	Navigation light indicators
			GOOD.
k	Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register
Foundation