

EA

COPY

Ship's name

"BREEZE"

Port

LYT

No.

5670

Last survey date 31.1.64.

Class is subject to

(holed) shell plate No. 1 in 2nd strake below sheer
(s.s.f) being specially examined and dealt with as
necessary next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: Wear and tear repairs to wasted doubling
plates on keel.

Recommendation

SUBMITTED record of DS 1,64 be assigned,
subject as above and to wasted doubling plates on
keel between frs. 10-14 and 20-27 from forward being
removed and keel plate in way being specially examined
and dealt with as necessary next drydocking.

DS 1,64 Subject.



© 2021

Lloyd's Register
Foundation