

Ship's name *SAINT CHRISTOPHER*

Port *Bahia*

No. *5661*

Class is subject to *None.*

Last survey date *15/12/65*

Repairs.

*Port boiler economies tubes found leaking & unit
was bye-passed - the Surveyor recommends that
the Port boiler economies be examined and dealt with
at Seattle when ship proceeds.*

*Note, subject as recommended.
For the information of the Committee.*

1/2/66.

*(B)
S.R.L. - Appendix Note
no change.*



© 2021

Lloyd's Register
Foundation

011803-011812-0145