

Ship's Name ~~SS/XXX~~ "SAINT CHRISTOPHER"
LR 519847 Gross tons 17888 JAN. 1966

Is there a rpt. 9? Yes Port Balboa, C. Z. Rpt. No. 5661

No. of visits 2. First date 14th Dec. Last date 15 Dec. 1965

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) HQ 3324

Date of completing rpt. 20-12-65 Surveyed at, if different from Port above Cristobal, C. Z.

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? No Freeboard Marks verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees
\$75.00

Damage fee
R

Expenses
\$10.00

S.A. fee

I have surveyed the above ship in accordance with the Rules for **Wear and Tear repairs.**

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

FOUND:

Two suction lines from the engine room double bottom tanks Nos. 2 and 3 to distilled and raw water tanks holed and wasted.

REPAIRS EFFECTED:

Two new suction lines fitted to existing flanges.

I recommend that this ship remain as classed ~~with~~/without fresh record of dry docking ; subject to all other conditions at present attached to vessel's class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

NEW YORK

JAN 19 1966

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

011805-011812-0146