

The class is subject to the bottom row of 4" tubes in the starboard boiler being examined by 7.57.

31 JUN 1957

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME "LAGOS MICHIGAN".

REPORT

Gen.

No. 22347.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

The above mentioned tubes now renewed.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED, without special conditions.

*End*

31.5.57.



© 2021

Lloyd's Register Foundation

011805-011812-0206