

E9 DEC 1964

Ship's Name ~~MS~~ "PEA COCK" LR 527244

Gross tons 159

Port of Registry Liverpool

Port Liverpool

Date of build 1960

Is there a Rpt. 9? yes

Rpt. No. 165242

No. of visits 2

First date 3.11.64.

Last date 5.11.64.

Interim Cert. issued &amp; copy herewith? Yes

Damage rpt. issued &amp; copy herewith?

Last rpt. (H.Q. only) L.V. 163641

Date of completing rpt. 16.11.64.

Surveyed at, if different from Port above Birkenhead

Surveyed afloat and/or in D.D. Drydock

Last date of examination in D.D.

Has a Load Line Survey been held? N.A.

Summer freeboard as verified -

CA 221 State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) (P.S.)

Survey fees

Damage fee

Expenses

comp SS £6

5/-

S.A. fee

I have surveyed the above-named ship in accordance with the Rules for Docking Survey and completion of Special Survey, Type "A" due 1,64.

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with ~~without~~ fresh record of dry docking 11,64, and to have the notation of S.S. 11,64.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee LIVERPOOL

David B. Henderson.

Minute

DS 11.64

S.S. 11.64

CS(M) 11.64

David B. Henderson.  
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation

011813-011822-0138 1/2 16.12.64



## Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~SS~~MS "PEACOCK"

Port Liverpool

X S.S. ( "A" ) Due 1,64

Rpt. No. 165262

In dry dock from 3.11.64.

In dry dock to 5.11.64.

Examined & conditionExamined & condition

Shell plating Good ✓  
 Sternframe Good ✓  
 Rudder Good ✓  
 Was rudder lifted? No  
 Plating, etc. in way  
 of shell openings Good ✓  
 Side scuttles  
 & deadlights  
 Overbd. scuppers  
 & discharges Good ✓

F.P. spaces

Chain locker Good ✓

A.P. spaces

Engine space

Boiler space

Under E. &amp; B.

Coal bunker

Tunnel &amp; well

Cement, asphalt,  
etc., on btm. shell

Weather decks Good

\* Casings Good

\* Deckhouses Good

\* Superstructures

\* Skylights Good

\* Companionways Good

\* Hatchways Good

\* Ventilators Good

Other items:

\* Air &amp; sounding pipes Good

Doubblers under " "

Steering arrangements (main) Good

" " (aux) Good

Windlass Good

Masts &amp; standing rigging

Hand pumps &amp; suction Good

W.T. doors

Bulwarks, freeing ports, etc. Good

EQUIPMENT:

Equipment letter

Fee ltr., if diff. from eqpt. ltr. (b)

Anchors: No. on board 1 B ✓

State if ranged Yes

Length on board 45 fms ✓

Cables { Mean dias. range from  $\frac{7}{8}$ " ✓ to

Rule length - Dia.

Mooring ropes Good &amp; Sufficient

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

30m,2,64 (MADE AND PRINTED IN ENGLAND)

LIVERPOOL

011813-011822-0138 2/4



© 2021

Surveyor to Lloyd's Register of Shipping  
David B. Henderson.

-8 DEC 1964