


COPY

LLOYD'S REGISTER OF SHIPPING

7380



Port B r e m e n

Date 17th September, 1964

This is to Certify *that I have surveyed part of the machinery of the S/S "WINAMAC" 11981 gross tons of Panama for Tailshaft Survey Continuous Liner, Main Boiler Survey and Continuous Survey of Machinery whilst the ship lay afloat and in dry dock at Bremerhaven on the 4th September, 1964 and subsequently and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* TB(CL) 9/64, MBS 9/64, CSM (with date) upon completion, subject to any outstanding condition of Class being dealt with as previously recommended.

Parts now examined:—

- Propeller and outside fastenings of sea connections.
- Port and starboard main boiler.
- Port and starboard main boiler safety valves adjusted.
- Sea connections.
- Port inboard aux. turbo generator engine.
- Stbd. steering gear pump.
- Emergency fire pump (in steering gear flat).
- Forward outboard feed water pump.
- Inboard main lub. oil pump.
- Starboard main condensate pump.
- Turbo driven fuel oil transfer pump (in forwd. pp. room)
- Fire and ballast pp. (in fwd. pump room)

K. E. Fedderwitz
 Surveyor to Lloyd's Register of Shipping
 (K.E. Fedderwitz)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

