

COPY

LLOYD'S REGISTER OF SHIPPING

7300



Port..... B r e m e n.....

Date..... 17th September, 1964.....

This is to Certify *that I have surveyed part of the machinery of the S/S "KINARAC" 11981 gross tons of Panama for Tailshaft Survey Continuous Liner, Main Boiler Survey and Continuous Survey of Machinery whilst the ship lay afloat and in dry dock at Bremerhaven on the 4th September, 1964 and subsequently and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* TS(CL) 9/64, MBS 9/64, CSM (with date) upon completion, subject to any outstanding condition of Class being dealt with as previously recommended.

Parts now examined:—

- Propeller and outside fastenings of sea connections.
- Port and starboard main boiler.
- Port and starboard main boiler safety valves adjusted.
- Sea connections.
- Port inboard aux. turbo generator engine.
- Stbd. steering gear pump.
- Emergency fire pump (in steering gear flat).
- Forward outboard feed water pump.
- Inboard main lub. oil pump.
- Starboard main condensate pump.
- Turbo driven fuel oil transfer pump (in forwd. pp. room)
- Fire and ballast pp. (in fwd. pump room)

K. G. Fedderwitz
 Surveyor to Lloyd's Register of Shipping
 (K.H. Fedderwitz)

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CSM Continuous Survey of Machinery
 DBS Donkey Boiler Survey
 ES Engine Special Survey

MBS Main Boiler Survey
 OF Fitted for oil fuel (date) FP above 150° F.
 SGS Steam Generator Survey
 SPS Steampipe Survey

TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed.
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

