

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

AIR MAIL

17 Battery Place,

New York 4, N. Y.

COPY FOR REPORT

December 4, 1957

The Secretary

LONDON

Dear Sir:

S/S "WINAMAC"
Bos. Rpt. 4793

The above report has been carefully considered by the American Committee at their meeting today in view of the very extensive nature of the alterations and renewals carried out.

As will be seen from this report, the ship is now completely new except for the ends, and has been increased in length by 38'-0", in beam by 6'-0" and in depth by 1'-9" moulded dimensions.


It is the owner's desire that, from a drilling point of view, this ship be now considered as new, and the next drilling survey be carried out 12 years from September 1957, this request being considered reasonable.

The Surveyor confirms that the end thicknesses show, from his check drillings, little or no deterioration whatsoever.

A drilling notation has not been assigned as this might imply that the ship required drilling in 8 years' time, the notation of "Rebuilt 57" being preferred as more aptly indicating the work now carried out.

Yours faithfully,

Principal Surveyor, U.S.A.



© 2021
Lloyd's Register
Foundation

011823-011825-0072