

"WINAMAC"


Before this case receives consideration, the Marseilles Surveyor should be referred to our letter of 19th November last, and be requested to state whether the following conditions of class have been dealt with:-

- (1) Defective tubes in main condenser to be renewed at the earliest opportunity but before the end of 12.55.
- (2) The main circulating pump motor control box apparatus and starboard boiler fan motor to be tested and dealt with at the next dry docking.

The Surveyor should further state what action has been taken regarding the re-examination of the L.P. turbine.

With regard to Item Nos. 29, 35, 36, 37, 41, 42, 43, 44 and 45, the Surveyor should state which of these (if any) are not applicable to the ship, as they appear in part to be outstanding for completion of the survey, as does the test of the main engines working and manoeuvring.

The Surveyor should confirm that his examination of the pumping arrangements was in accordance with Chapter C. para. 402 of the Rules.

*Install also 6
stand if you
will*
More *you*


31.1.56.

For clsg to rule (H r m) :-



© 2021

Lloyd's Register
Foundation

01823-011825-0083