

C.K.

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS~~ "MASTER ELIAS"

LR 522852

Gross tons 5500

Port of Registry Piraeus

Port ROTTERDAM

Date of build 10-1938 Is there a rpt. 8? yes

Rpt. No. 60180

No. of visits 2

First date 1-3-1965

Last date 3-3-1965

Interim Cert. issued & copy herewith? yes

Damage rpt. issued & copy herewith? no

Last rpt. (H.Q. only)

Date of completing rpt. 12-3-1965

Surveyed at, if different from Port above

Is a rpt. 9A attached? no

MN (428)

Nature of survey T.S. and S.R.L.

Survey fees T.S. Fl. 75,--

Damage fee

Expenses fl. 2.-

S.A. fee

DOCKING

Propeller good

Sea connections

Oil gland -

Wear down of stern bush (if relined, state clearance before and after) lower half rewooded. clearance before 6.2 mm., now 1 mm.

Fastenings good

Has screw/~~xxx~~ shaft been drawn? yes

Date of examn. -

Has shaft been changed? no

Has shaft now fitted been previously used? -

Has shaft now examined/~~xxxx~~ a continuous liner? yes Approved oil gland? no

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to { Sat Spt

Boiler securing arrangements

Main economisers

Steam heated steam generators

Forced circulating pumps

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Exhaust gas heated economisers and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/~~xxxx~~ fresh record of

T.S. (C.L.) 3-65 now without the subject regarding the propeller.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

P.J. Stuy.  
Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

FRIDAY 23 APR 1965  
As now without spec  
TS 3. 65

Lloyd's Register Foundation

011826-011833-0031

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		l Generators & governors	
b Exciters		m Motors	
c Air coolers		n Switchboards & fittings	
d Motors		o Circuit breakers	
e Air coolers		p Cables	
f Control gear cables, etc.		q Insulation resistance	
g Insulation resistance		r Steering gear generators & motors	
h Insulating oil test		s Navigation light indicators	
i Overspeed governors			
j Magnetic couplings			
k Air gap			

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

S.R.L. 232

Propeller sent to Messrs. Lips and permanently repaired.

Re stamped:

Reconditioned: LLOYD'S ROT. WB 4-3-65 (Certificate attached).

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.