


COPY

LLOYD'S REGISTER OF SHIPPING



Port. PLYMOUTH

12th February, 1965.


This is to Certify that I have surveyed part of the machinery of the S.S. "MASTER ELIAS" 5500 Gross tons, of Piraeus, for Part M.B.S. as the vessel lay afloat at Plymouth on the 9th February, 1965 and subsequently

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned with fresh record of M.B.S. 2,65 when the survey has been completed.

Parts now examined:—

Port and Starboard main boilers throughout together with safety valves and mountings.

To complete the boiler survey the centre boiler remains to be examined throughout, together with safety valves and mountings, all three boilers to be examined under steam and safety valves adjusted, also oil burning system and remote controls to be examined.


R. M. Nicholson.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150°F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."