

Ship's name

"SHELL MANAURE"

Port

CCO

No. 6727

Last survey date 13.3.63

Class is subject to NIL

MBS due 12.62 now held.

Docking, both screwshafts examined.

Repairs

Port screwshaft found cracked at large end of taper and now rejected. Previously used spare screwshaft with new liner now fitted to place. Both stern bushes re-wooded and oil gland discarded. Air heater tubes now removed from both boilers.

IT IS SUBMITTED that this vessel is eligible for the records MBS 2.63 and Both TS CL 3.63.



EW
© 2021

16.5.63

Lloyd's Register
Foundation