

COPY



LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

ENCLOSURE

Please address further
communications on this subject
to THE SECRETARY
and quote the following
reference

12th May, 1964

Classn. (R)
(H)

Dear Sir(s),

Recent figures indicate that screwshaft failures in ships of 'Liberty' or 'near-Liberty' type continue to occur at a higher rate than in other ships, and in view of this the Committee consider that the interval between surveys should not exceed the three years prescribed by the Rules.

Consideration will, however, be given to the circumstances of any special case if Owners can show that they have taken positive steps in an effort to reduce the risk of failure, and the precautions recommended by the Society are given on the attached sheet.

The Screwshaft Survey of your steamer
"SAJANY" will become due in
August 1964 and, as this is one of the type
ships referred to above, I shall be glad to learn
that you will comply with this inspection at
about the due date.

Yours faithfully,

R. N. Cook

Clerk to the
Classification Committee.



© 2021

Lloyd's Register
Foundation

011834 - 011843 - 0238