

18 JUL 1963

EA
Ship's name "SHOSEI MARU"(Port KOB. No. 11663

Last survey date 31.5.63.

Class is subject to

rudder stock liner being specially examined
and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~or none~~ ~~XXXXXXXXXX~~)

Nature of present survey (afloat and in drydock)

Docking: Damage repairs - grounding and contact,
including renewal of rudder stock liner as above.

Recommendation


SUBMITTED record of DS 5,63 be assigned,
subject to rudder stock liner (fractured in
way of gland packing) being specially examined
and dealt with as necessary next drydocking.

DS 5,63 Subject
amended.

IN S.R.L. APPENDIX.

(Main structure partly of P.403 Steel).

Shell plates A.5 & 6, B.6 indented.



© 2021

Lloyd's Register
Foundation

CSS. Records Dept.
to note.

S.P.K.
5/7/63

018344-01850-0219

X