

(Req. 1a.)

(Received at London Office

5 APR 1948

No. 454 Place GOTHENBURG Date March, 19 48.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 113 building by Messrs. Uddevallavarvet AB., Uddevalla for Messrs. Yacimientos Petroliferos Fiscales of 9000 Tons. Length 480'-0", Breadth 64'-0", Depth 35'-6" intended to be Classed +100A1 Carrying Petroleum in Bulk. Long framing. El. welded.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers Nordberg M.F.Y. Co, Milwaukee, U.S.A.

Boiler Makers

Signature UDDEVALLAVARVET AKTIEBOLAG

To the Secretary, Lloyd's Register of Shipping, 71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Recd 22/14/4

011860-011868-0211

the double bottom tanks in the engine room and water ballast in fore- and after peak tanks.