

CLASS IS SUBJECT TO:

- (1) Screwshaft cone being specially examined at the next Screwshaft Survey.
- (2) Metalock repairs to Main Engine water space division plates being specially examined ~~on completion of present fishing voyage.~~ 8/12/62

m.v. "MAGNOLIA".

GMS 29344

Before this case receives consideration, the Surveyor should be asked to clarify whether he considers the oil gland should be renewed at the next Screwshaft Survey, in view of the temporary repairs now made. If so, an amended Certificate should be issued with a copy to this Office.



^{End}
© 2021
20.9.62.

Lloyd's Register
Foundation

011890-011895-0125