

"MAGNOLIA"

Before this case receives consideration IT IS SUBMITTED that the Hull Surveyors be asked if they are able to state if the new bronze propeller now fitted is of the same design as the propeller for which the torsional vibration calculations were made (Amsterdam Rpt. 17101 dated 10,49). If this information is not available the weight and moment of inertia of the new propeller should be ascertained and forwarded to this office.

The Surveyors should also state if the main engines are fitted with crankcase explosion relief devices (Circ. 2045)

It is concluded that the Surveyors are satisfied with the condition of the remaining machinery (Secretary's letter dated 13.12.54) but this should be confirmed.

The Surveyors should state the number of auxiliary air receivers, if any, fitted.

RL

1.4.55.

Clg ltr Hul

RL

16/4



© 2021

Lloyd's Register
Foundation

011890-011895-0204