

20c, 0, 18.

1

X Scott & Sons, Bowling, Glasgow.

Yard No. 388.

TAFRASH

Similar vessel to the "TABAS", "TAFTAN" etc.

Sent to Chief Surveyors.....

CB

Received from Chief Surveyors.....

TAFRASH

VESSEL'S NAME Steel Tw. Sc. Tug "TANB"

REPORT

Gls.

No. 73836

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Nature of Survey FIRST ENTRY

When due.....

This Tug is fitted with "Kort" nozzles.

40077

+100A1 "For Towing Services in the Persian Gulf" "Fitted for oil fuel 4.49 FP above 150°F"

3.49 Bwg.

Wing tanks in boiler space 15t, DTf 7', 12t, FPT 15t, APT 13t

FK, 3BH, Cem., Lloyd's A & CP

O.L. 110.2'

 $\frac{1}{8}$ "

© 2021

Lloyd's Register
Foundation

011896-011904-0106

issue cert. Rm

Are the scantlings and arrangements in way of the Bottom Forward in accordance with the Rules and/or as approved ?.....

Do. ✓

BEAMS.

Uppermost Continuous Deck, amidships