




LLOYD'S REGISTER OF SHIPPING

17 Battery Place,

New York, N. Y. 10004

29th December, 1965



The Secretary,
LONDON

M.V. "SOBRIETAS"

Dear Sir:

We would refer to the Kingston Surveyors
Report 8, No. 9804.

The Surveyor has now advised us as follows:

"With reference to your letter of the 3rd instant re the above vessel, the temporary repairs to the fore peak tank were carried out at Rio Haina, D.R., after the vessel grounded on the 16th July 1965, by the ship's crew, and the Captain states that the cement box that has been fitted is suitably re-enforced with steel wire and wire mesh."

Yours faithfully,

W. J. ROBERTS
Chief Representative and
Principal Surveyor



© 2021

Lloyd's Register
Foundation

011896-011904-0165

SR

REPORT

CSA

4/1/66
50.



© 2021

Lloyd's Register
Foundation