

LLOYD'S REGISTER OF SHIPPING

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name ^{SAN ROBERTO}
"PACIFIC BREEZE"

Official No. 180963

Port of Registry HONG KONG.


This ship has been under survey at Hong Kong,

on 30th July, 1962, ~~196~~ and the following alterations to the conditions of
assignment of loadlines have now been effected/~~found~~:—

Tonnage hatch closed by welded steel W.T. hatch cover.

Tonnage well scuppers permanently blanked off on ship's side.

Locking bars provided for each section of covers on shelter deck hatchways.

All shelter deck hatch beams stiffened with 6" x .50" flat bars welded
to underside of bottom flange.Openings in port and starboard 'tween deck bulkheads fitted with welded
studs and steel plates with watertight joints fitted.Open shelter deck freeboard markings obliterated and closed shelter deck
freeboard markings verified.

D.C. Wood.

Surveyor to Lloyd's Register.

Hong Kong.

30th July, 1962.

17/9/62
17/9/62



© 2021

Lloyd's Register
Foundation