

19 OCT 1933

Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Steel Sc. "SUPERIOR" Report Lon No. 99232a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2A/6/92.)

ure of Survey _____ When due _____

The Screwshaft Survey became due in 7,33.

In reply to enquiry the Buenos Aires Surveyors now forward a copy of a letter received from the Owners stating that they do not propose to continue the class of this vessel.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...

Y. H. H.
19.10.33



© 2021

Lloyd's Register
Foundation

011947-011954-0206