


FS/AG.



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

18 FEB 1953

12, Royal Exchange Chambers, Boar Lane,

Leeds, 1

Telephone No. 23666

17th February, 1953.

Reference

Dear Sir,

Classn.

C.

Philip & Son Yard No. 1241.

Hyland Steering Gear.

We duly received your letter of the 13th instant regarding a pump No. PF.1760 stated to be fitted to the above Steering Gear. In reply, we have to advise you that Messrs. Hyland Ltd. (now Vickers Armstrongs Ltd.) state they have not dealt with Yard No. 1241, but a Steering Gear No. 999 for Yard No. 1245 was built under survey and is covered by our Certificate No. C.18608, and bearing in mind that each Steering Gear requires a Pump as an integral part of the Gear, the Pump, whilst not specifically referred to, is included in this Certificate and was inspected at the time the gear was tried on completion.

Our Certificates now bear reference to the various parts of the gear, to obviate any further misunderstanding.

Yours faithfully,
The Surveyors.

Per:

The Secretary,
LONDON, E.C.3.

2021
Lloyd's Register
Foundation

012003-012010-0124

CLASSIFICATION

C Re

the enclosure

the enclosure

begin of the year to operate any further administration

on completion

in this Commission and are interested in the future the best are the best

best the best matter not specifically mentioned to be included

that each person's best interests are taken into account

the enclosure

© 2021

Lloyd's Register Foundation



Goods

Royal Exchange Chambers, Boat Lane

LISTED WITH THE BRITISH COMMERCE REGISTER

ROYAL EXCHANGE CHAMBERS, BOAT LANE

10/10