

SHIP'S NAME

'STANROYAL'

REPORT

Rot.

No. 34169

Outstanding Conditions of Class: Subject to buckled centre line bulkheads Nos. 2 & 3 lower holds being dealt with at next drydocking, to indented bottom and side shell plating (p & s) being specially examined and dealt with as necessary by next Special Survey, and to 15 fathoms of chain cable being supplied at the earliest opportunity.

Endorsement of Class (B) (As before ~~or None~~)

Surveys due: ✓

Nature of Present Survey: (~~Afloat and~~ in dry dock)

Docking, Damage (H.W.) Repairs and Equipment.

Special Features:

Is Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)

S.S. to be completed by:

Recommendation: SUBMITTED record of docking 9,51 be assigned, subject to indented bottom and side shell plating (p & s) being specially examined and dealt with as necessary by next Special Survey, but without other condition.

9,51 Rot. Subject
Without.

ENDORSEMENT OF CLASS (B).

✓ Indents in bottom plating, etc. in way of A.P. and in side shell plating (p & s).

R.S.P.
31.12.51
C.S.S. Records Dept.
to note: fractured longitudinal bulkhead plating.



Lloyd's Register
Foundation

012003-012010-0231