

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 10 When handed in at Local Office 14 SEP 1901 Port of BARRY.

No. in Reg. Book. Survey held at BARRY Date, First Survey 10 Sept 1901 Last Survey 10 Sept 1901
on the Wood, Iron or Steel 5 Roma Master
TONNAGE:- Built at Sunderland By whom J L Thompson & Sons Ltd When 1901
GROSS 3599 Owners b Marwood Port belonging to Whitty
UNDER DEK 3439
NET 2354 Owners' Address
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Leaving D. Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

How done:- Vessel placed in dry dock, bottom sighted, Chained and coated

SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Windlass	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stems ditto	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	length size
Reverse Frames		Ditto ditto at other places ditto	Rule length size
Floors		Stringers, Clamps & Shelves ditto	Hawsers & Warps
Keelsons		Salting ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is now in good condition and eligible, in my opinion, to remain as classed and to have record of survey 9.07.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fee applied for,	£
Survey Fee (per Section 28)	£	Received by me,	£
Special Damage or Repair Fee (if any) (per Sec. 28.)	£		£
Travelling Expenses (if chargeable)	£		£
Second Surveyor's Fee (if any)	£		£

Committee's Minute
Character Assigned

FRI. SEP 20 1901

100A1 Steel

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

012011-012018-0245

012011-012018-0246