

S. S. Roma

Submitted that before dealing with this case it be pointed out to the Surveyor that the <sup>new</sup> rule requires the <sup>screw</sup> shaft to be 14 1/16" with a propeller 16" dia and in view of its not being fitted with a continuous liner; and he should be requested to explain how it is that the screw shaft fitted is ~~that~~ so much smaller than is required by the rules for the proposed working pressure of 160 lbs.

hr to Sld 17/9/01

17.9.01  
Lloyd's Register  
Foundation

012011-012018-0247

Number of water ballast tanks, six tanks

Round of beam