

4955

M'wood

15256

# FREEBOARD VERIFICATION FORM FOR STEAMERS.

Newcastle-on-Tyne

When received in London Office

10 FEB 1923

Vessel's Name **S/S 'NICOLAOS' EX ROMA**

80208

Special No. **113729**

No. in Reg. Book **71549**

Port of Registry (For Foreign Vessels) **ANDROS.**

Material **Steel** State whether Classed by Lloyd's Register **Yes**

Signature of Owners *will be forwarded when received from the Agents* Date of Verification **8th Feb 1923**

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	<b>5</b> ft.	<b>1</b> ins.
From centre of disc to top of statutory deck line at awning or part-awning deck	<b>✓</b> ft.	<b>✓</b> ins.
Fresh Water line above centre of disc		<b>6½</b> ins.
Indian Summer line above centre of disc		<b>4½</b> ins.
Winter line below centre of disc		<b>4½</b> ins.
Winter North Atlantic line below centre of disc		<b>✓</b> ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of <del>wood or steel</del> deck with the vessel's side	at <del>main, spar or upper dk.</del>	<b>2</b> ins.
	at <del>awning or pt.-awning dk.</del>	<b>✓</b> ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a ~~wood or steel~~ deck.

*certificates desired. The original freeboard certificates are enclosed for cancellation*

J.R. Macleod, Surveyor.

(To be filled up in London Office.)

Document No. **15256** Date of Committee's Minute **3.5.06**

Particulars for record Register Book.	Moulded Depth	<b>27</b> ft.	<b>6</b> ins.
	Freeboard	<b>5</b> ft.	<b>1</b> ins.
	Corresponding Draught	<b>22</b> ft.	<b>10</b> ins.

Boards compared and found correct by *W.D.* Date **12.2.23**

Fee paid? Form for Certificate

Instructions Date

Certificate written **12th Feb. 23** Noted for posting

*Fee £1.1/.*  
*Applied for 9/2/23.*

012011-012018-0282

RD recommended amidships from centre of Disc to top of

This submitted  
certificates be sent  
for issue when the  
hatchways support are  
found or made equivalent  
to rule requirement  
The surveyor should forward  
full particulars on back  
of 116 form. W.D.  
12.2.23



© 2021

Lloyd's Register  
Foundation