

14 AUG 1931

Ferry "MANECO".

IT IS SUBMITTED that this vessel's machinery is eligible for the record *LMC 6,31.

In reply to enquiry the Halifax Surveyors state that ~~the~~ discharge valves have not been fitted to the ship's side as required by the Rules, and that the air receivers are welded at the landings at the ~~plate and~~ butt strap edges.

IT IS SUBMITTED that these matters might be accepted in this instance, but the Surveyors should be informed that in future cases where it is desired to make departures from the Society's Rules the matter should be submitted for consideration before the work is put in hand.

Handwritten: L.H. 12/8/31

Handwritten signature: J.P.K.
Handwritten initials: J.

Handwritten signature: J.A.
14.8.31.



© 2021

Lloyd's Register Foundation