

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Steamer "ANDROS VENTURE"
Official Number 194857 Port of Registry Montreal
Owners Andros Shipping Co., Ltd. (Atlantic Shipping Agencies Ltd., Managers).
Builders, and where and when built Davie Shipbuilding and Repairing Co., Ltd., Lauzon, P.Q.,
November, 1953.

REGISTERED PARTICULARS

Length	603.9 feet	Tonnage, Gross	17844.98
Breadth	84.2 feet	Ditto under Deck	16642.32
Depth	44.2 feet	Ditto Net	13279.76

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 9th November, 1953 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character **100A1** Carrying Petroleum in Bulk Fitted for oil fuel 11,53 flash point above 150°F. subject to Periodical Surveys as required by the Rules.


The approved minimum freeboards from the deck line are as follows:—

Tropical	10 feet	3 1/2 inches (T).	Winter	12 feet 2 inches (WNA).
Summer	10 feet	11 1/2 inches (S).	Allowance for fresh	
Winter	11 feet	8 inches (W).	water for all freeboards	

Witness my hand,



pro Secretary.



Chairman.

71, Fenchurch Street, London, E.C.3. 11th June, 1954.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.


This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."




© 2021

Lloyd's Register
Foundation



012027-012031-0010



© 2021

Lloyd's Register
Foundation