



LLOYD'S REGISTER OF SHIPPING

Rooms 9-12, Shipping Offices,

Port Main Entrance, Wharf Road,

Box 177
P.O. ~~Bag 10007~~, Apapa, Nigeria

22 JUL 1964

Telegrams: Lloydsreg, Lagos

8th July, 1964.

Telephone No. 55311

Reference

C
AH/CB

Dear Sir,

BARGE "AFFET 6"

With reference to your letter dated the 21st April, we now forward herewith a report on the above barge by Mr. R. L. Floode the Acting Surveyor at Freetown.

You will note that attention is drawn in the report to the fact that there were no portable fire extinguishers on board the vessel and we shall be glad to learn what is required for this barge and whether this should be made a condition of class before issuing an Interim Certificate.

Yours faithfully,

H. Floode

pp: SURVEYORS.

The Secretary,
LONDON.

Enc:



© 2021

Lloyd's Register
Foundation

012047 012057 0173

SR
REPORTS

Refer to Engine
Room Dept

It is considered this barge should be
provided with 1 portable fire extinguisher in
the pump room, 1 at the forward end of the deck
and 1 at the after end of the deck.

23/7/64

29/7/64

Before this receives Glasgow
consideration requested to
should be requested to
forward the plan of
pumping arrangements.
YJB
30/7/64

The surveyor
should be advised
in the terms of the
foregoing and advised
that the condition of the
class should be requested to
confirm whether the surveyor
best submission to be
classified completed. YJB
12/8/64

Enc:
TOMSON
The Secretary

condition of class before
required for this barge
on board the vessel and
to the fact that there
for will note that a

Mr. G. I. Moore the
is now (Lloyd's Register &
With reference to Lom.



© 2021
Lloyd's Register
Foundation

8th July, 1964
B.O. B...
Box 11
Port Main Entrance
Rooms 9-13, Shipping Offices
LLOYD'S REGISTER OF SHIPPING