

Received from Chief Ship Surveyor..... -7 JUN 1961

SHIP'S NAME "VASCO" REPORT Bbo. No. 13068
GB

Outstanding Conditions of Class: NONE.

S.R.L. Appendix. (~~As before~~ None)

Surveys due: A SPECIAL SURVEY (C) became due 1,61.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Principal part of the Special Survey: Repairs on account of various damages: Equipment - 60 fms. of c.c. found worn: Alteration to A.P.tank.

Special Features:

Is Interim Certificate in order (Yes-No ~~None~~)

~~Items Outstanding~~ (If any for ~~S.S.~~)

TO COMPLETE THE S.S.:- Freeboard marks to verify.

Numerous frames (p & s) and some shell plates (p & s) to renew (see Page 2 for details).

S.S. to be completed by:

Recommendation:

SUBMITTED record of 'DS 2,61' be assigned as recommended, subject to wasted shell frames (p & s) and shell plates G.8 and H.8 (p.s.f) and G.4 & 9, H.8,9 & 10 (s.s.f) being examined and dealt with as necessary also to 60 fathoms of chain cable being renewed by completion of the Special Survey, but ACTION be DEFERRED for completion of the Special Survey.

DS 2.61 Subject.

S.S. PART HELD.

AMEND R.B.

FROM:- APT 22t.

TO :- APT 91t.

G.S.S. Records Dept.
to note.

From:- (h)

To :- h

P.T.O.

Blk(new)

The proposal to defer repairs to the wasted shell plating frames (p & s) and shell plates etc. mentioned above has been approved (28.2.61)

012089-012095-0159

KN 2.62

See letter
2/16/44

IT IS FURTHER SUBMITTED the Surveyors be requested to furnish the mean worn diameter of each of the 4 lengths of chain cable now condemned.

They should also be advised that the freeboard marks require to be verified.

W.B.I.
25.6.64



© 2021

Lloyd's Register
Foundation