

La correspondencia
debe dirigirse a los
Inspectores

Ref:Classⁿ

LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3

Calle Gran Vía, 83, 1.º izqda.

Apartado de Correos N.º 286, Bilbao

Telegramas: Register, Bilbao

17th February, 1961

Teléfono 16995

RECEIVED

22 FEB 1961

Dear Sir,

S.S. "VASCO" R.B.Nº 84905

The above vessel is at present in this Port, with the object of undergoing Special Survey (due 1.61) but amongst other repairs it was found necessary to recommend renewal of a number of shellframes in holds, and the renewal of several sheerstrake plates on account of grooving.

Unfortunately the dry dock position is such that, in view of dock bookings the Repairers could only allow the Owners a very limited stay in dock, during which time they have carried out the examination and testing of tanks.

In view of the above, the Owners have offered to reinforce now those frames which we consider necessary, and have stated that they will renew the frames now recommended at the next dry docking.

They have also requested that, as the ship will have some time in dry dock for the renewal of the frames, we defer until then the renewal of such shell plates as we consider could reasonably be deferred for one year.

From the examination now held we consider that this is a reasonable request and we would be glad to have confirmation that it will be in order to recommend a notation of S.S. 2.61 subject to completion of the Special Survey before the end of February, 1962.

Yours faithfully,

The Secretary,
LONDON

For the Surveyors.

012089-012095-0161


SP

CLASSIFICATION

H

Submitted for Approval
g. H. H. 22
261

M



© 2021

Lloyd's Register
Foundation

2020 21.11.20 "COSAS" .2.2

1987, 1988, 1989, 1990

CHANGES TO REGISTERED SYMBOLS