

GB Ship's name "AUSTRALIAN PROGRESS" Port NSW No. 9171

Last survey date 24.4.67

Class is subject to

indented shell plating in 1st and 2nd below sheer and internal structure in way of Emergency fire pump room (p.f) and to indented sheerstrake (p) and frame 46 in way being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (~~as xxxxxxxxxx~~ none)

Nature of present survey (~~xxxxxxx~~ in drydock)

TO NOTE		TRC
S. PLANS	S. REPAIRS	
FREEBOARD	E. REPORTS	PUBS.

LLS Hired 14/4/67

Docking: Annual Survey: Damage (contact) involving shell plate G.11 (p).

Recommendation

SUBMITTED records of 'DS 4,67' and 'AS 4,67' be assigned, subject as above, and to indented shell plate G.11 frs.71-75 (p) being specially examined and dealt with as necessary at the next drydocking.

DS 4,67  
AS 4,67 Subject

IN S.R.L. APPENDIX

(Main structure partly of Grade 'D' Steel)  
Bottom shell plating pitted.

Shell plating G.11 (p) indented.

Sheerstrake in way of dry cargo hold (s) forward slightly set in.