

COPY

LLOYD'S REGISTER OF SHIPPING



Port.....GENOA

Date.....8th February, 1967.

^{we}
This is to Certify that ~~I~~ ^{we} have surveyed part of the machinery
of the M/V "IRCANIA", 12493 gross tons of GENOA
for ABC - CS & DS, as she lay afloat and in drydock at this port on
1st February, 1967 and subsequently,

and that all ~~my~~ ^{our} recommendations have been carried out to ~~my~~ ^{our} satisfaction. ~~I~~ ^{we}
~~am~~ ^{are} reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following
survey records assigned ABS (with date) as previously recommended and
CS (with date) when the surveys have been completed, subject to any
outstanding conditions of class being dealt with as previously recom-
mended. To complete the ABS the exhaust gas heated boiler safety valves
to be adjusted under steam.

Parts now examined:—

FOR D.S.

- Propeller and underwater fastenings.

FOR C.S.M.

- M.E. No.1 cylinder, liner, cover, piston & rod, valves and gears.
- No.2 (Port Pwd) aux. Diesel engine main bearings and journals, bottom end bearings & crankpins.

FOR A.B.S.

- Starboard auxiliary boiler (oil fired) examined in its entirety.
- Starboard auxiliary boiler safety valves adjusted under steam.
- Exhaust gas heated boiler examined in its entirety.

TO COMPLETE THE A.B.S. the exhaust gas heated boiler safety valves to be
adjusted under steam.


(A. ANSALDO & C. TEODORI)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers Servants or Agents of the Society."

012108-012112-0220