

CARDIFF Report No. 61752.

COPY of this Certificate forwarded to Oslo Surveyors.

LLOYD'S REGISTER OF SHIPPING



Port C A R D I F F.

29th June, 1962.

This is to Certify that I have

part of
Surveyed/the Machinery of the m.v. "MARICOPA", 11342 tons gross of
Tonsberg on the 13th June, 1962 and subsequently while the vessel
lay in drydock in Barry and afloat for Docking, Continuous Survey,
Auxiliary Boiler Survey and the fitting of crankcase relief devices,
and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
ABS 6-62 now and CS with date on completion,
and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

Main engine No. 4 side and centre connecting rods, top ends and guides.
Main Engine No. 4 side and centre crankpins and bearings.
Forward and after steam generator engines.
Sea valves:- Condenser overboard discharge valve, F.W. cooler
overboard discharge valve, forward main pumproom sea suction port
and starboard, aft main pumproom sea suction, port and starboard,
lub oil cooler overboard discharge valve.
Crankcase explosion relief devices.

A. R. Norton & J. S. McCullagh
(A. R. NORTON) Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 50m,3,58 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register
Foundation

01213-01216-0019