

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

29. APR. 1963

Ship's Name ~~SS~~/MS

"CHARLES H. MACKAY"

Gross tons 799

Is there a rpt. 9?

~~XXX~~ Yes-9B.

Port Melbourne

Rpt. No.

20436

No. of visits

Two

First date 19.9.62

Last date

9.4.63

Interim Cert. issued
& copy herewith?

No

Damage rpt. issued
& copy herewith?

No

Last rpt. (H.Q. only)

Date of

completing rpt.

24.4.63

Surveyed at, if different from Port above

Surveyed afloat

and/or in D.D.

Both

Last date of examination in D.D.

Has a Load Line

Survey been held?

-

Freeboard Marks verified

Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

-

-

-

S.A. fee

-

I have surveyed the above ship in accordance with the Rules for Condition Survey after completion of a voyage from the United Kingdom to Australia.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

The vessel examined afloat and in dry dock and all found in good condition.

The Service freeboards have been remarked and verified as per the attached Rpt. C12 a and the voyage marks obliterated.

I recommend that this ship remain as classed ~~with~~ without fresh record of dry docking

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate)

Date of Committee

Minute

See Rpt. 1.

(SGD) J. E. North.
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

012129-012141-0034