


26 JAN 1955

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Cert. No. 3302

Port BREMEN

26th January, 1955

This is to Certify that

A. Holtz

the undersigned Surveyor to this Society did at the request of Messrs. Deutsche Mc.Gregor C.M.B.H., Bremen, attend the works of Messrs. Louis Wessel K.G., at Bremen, on 19th January, 1955, and subsequently for the purpose of examining and testing

19 Electric Welded S.M. Steel Hatch Covers

made to the order of Messrs. Howaldtswerke A.G., Kiel and intended for the converted iron ore carrier M.T. "EUROPE", Owners K. Salveson & Sønner of Kragerø, as follows:

| | | | |
|---|-------------------|---------|------------------------------|
| 4 | hatch covers nos. | 1,2,3,4 | for hatch No.1 |
| 4 | " | " | " 5,6,7,8 for hatch No.2 |
| 3 | " | " | " 9,10,11 for hatch no.3 |
| 1 | " | " | " 12 for hatch no.4 |
| 4 | " | " | " 15,16,17,18 for hatch no.5 |
| 3 | " | " | " 19, 20, 21 for hatch no.6 |

The hatch covers have been examined, material, dimensions and scantlings checked and found in order and in accordance with the approved plan No. 774 E, dated Hamburg. 18th December, 1954.

The Society's Rules for Electric Arc Welding have been complied with and approved electrodes have been used only. The workmanship was found to be good. The hatch covers for each hatch have been fitted together, examined and the cross joints wedged, examined and found in order.

For identification purposes the above 19 hatch covers have been stamped:-

| | |
|-----------------------|------------------|
| Hatch Nos: 9,10,11,12 | LLOYD'S NO. 3302 |
| 19,20,21 | A.H. 19.1.55 |
| | A.H. |

| | |
|----------------------|------------------|
| Hatch nos: 1,2,3,4,5 | LLOYD'S NO. 3302 |
| 6,7,8,15,16, | A.H. 21.1.55 |
| 17,18 | A.H. |

Fee DM 250.00
Exp. DM 5.00

This Certificate is issued upon the terms of the Rules and Regulations of the Society. While the Committees of the Society use their best endeavours to execute, it is to be understood that neither the Society nor any Member whatever to be held responsible for any inaccuracies in the Register Book or other entries in the Register Book or other documents issued by its Committees or any Member thereof.



© 2021

Lloyd's Register Foundation

1220-FR10-0221