

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

## Certificate of Class

Motor Tanker "PULBOROUGH".  
Official Number 300994 Port of Registry London  
Owners Stephenson Clarke Ltd.,  
Builders, and where and when built Rolandwerft G.m.b.H., Bremen, 1956.

REGISTERED TONNAGES  
Gross 942  
Net 459

MOULDED DIMENSIONS  
Length 194' 5"  
Breadth 31' 2"  
Depth 15' 3½"

This is to Certify that this Ship has been surveyed by the Surveyors to this Society, and was reported to be, on the 13th October, 1959 at North Shields in a fit and efficient condition and in accordance with the Rules; also that she has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character **100A1** Oil Tanker subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	—	feet	11	inches (T).	Winter	1	feet	8	inches (WNA).
Summer	1	feet	2½	inches (S).	North Atlantic	1	feet	8	inches (WNA).
Winter	1	feet	6	inches (W).	Allowance for fresh water for all freeboards	3½	inches		

Witness my hand,

W. J. Ferguson.  
Secretary.


Kenneth A. Bell  
Chairman.

71, Fenchurch Street, London, E.C.3. 4th December, 1959.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation