

s/s "Clan Donald."

It is submitted that the Greenock Surveyors should be requested to state whether they have correctly reported the area of the main electric light cables as .300 sq. ins. whereas the area of the cables carrying 277 amperes by the Rules requires to be .342 sq. ins.

Ln:- 5/4/17

JWZ.

5/4/17.

Lloyd's Register
Foundation

012148-012158-0147