

How "Reynella"

F.E.

of Ship Surveyor

Received from Chief Ship Surveyor

AME Stl T.S.M.V. "REMO"

Rpt. 2i

No. 7409

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

verse No. 16936

Depth "d" ✓

ng: Table No.

Description Bull angle + Channel frame

tudinal No. 46990

as approved

Proportions Length 13.87
Depth =

Deck Sheerstrake as approved

Revised Rules

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
ssed

✱ 100 A.1. (Steel).

2 Dks (Stl), 3rd Dk (Stl) in No 1.2.3 Holds

Cell D.B. 426' 16975, F.P.T. 2275, A.P.T. 1845.

F.K, 8 B.H, pt cm, Lloyds A. C.P.

P 31', B 214', F 47'.



© 2021

Lloyd's Register
Foundation

012159-012164-0059

8.12.27.