

3rd October, 1958.

ALEXANDRIA.

965 - As recommended.

964 "AGNETE TORM" As recommended, a notation of DBS 8,58 having been assigned.

954 "ATHAMAS" As recommended, except that the notation of .S. Alx. 7,58 has been withheld pending the equipment being placed in accordance with Rule requirements. In this respect I would point out that the Rules require that in this case 70 fathoms of chain cable should be on board. It will be seen, therefore, that in addition to 45 fathoms of worn chain cable which require to be renewed, 30 fathoms of chain cable remain to be supplied. In these circumstances, I shall be glad if you will issue an amended Interim Certificate.

Concerning the machinery, it is considered that the class should be made subject to the propeller being renewed at the first opportunity, and an amended Cert.B.1. should also be issued incorporating this item.