

11
- Reference
Class

E X T R A C T FROM ROT. CL.LTR.2.3.55.

"GILIJANG". I am in receipt of your letter of the 28th February, the contents of which have been noted. I have to point out, however, that it is not necessary to fit crankcase explosion relief devices when the cylinder diameter is below 6".



© 2021

Lloyd's Register
Foundation

012221-012228-0111