

(Received at London Office,.....)

Admin 15M

Port

Date

19

We request that the Lighthouse Tender

Building

Trinity House

by J.S. White & Co. Ltd.

1220

Tons.

Length,

207'-0"

breadth,

37'-6"

depth,

16'-0"

To Class Lloyd's 100 A.1 Special Service

be Specially Surveyed while building (

(Lighthouse Tender)

If for a particular term or class, state the same

We hereby engage to pay the established Special Survey Fees or any variation therefrom which has been duly notified and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or for any other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

2007 in Builder's Yard.

Manufacturers of Engines

English Electric Co. Ltd.

Form of Authorisation

sent to Ditto

of Boilers

18/3/57

Signature



The Secretary, Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

012256-012264-0010

etrically we

e.

None

ed by the

CATED

ING, CAS
(Certificat

ting.

ring.

ing.

ic

one

None.

Are cargo battens fitted in holds?

No. in 'tween decks?

No.

Signal

To., D

Whet
Fo

Br

Numb

Numb

Rigged

Stem

Stern

Build

Frame

of vo

Numb

No. of
jets of
engines

Four

No. of
Shafts

Two



© 2021

Lloyd's Register
Foundation