

S.S. "HELLAS"

Pir. 8965

Before this case receives consideration  
it is Submitted the Surveyors be informed that  
the certificate covering repairs to main engine  
turbines in Italy has not been attached and is  
awaited.

*Ewh*

30.5.61.



© 2021

Lloyd's Register  
Foundation

012265-012272-0021