

25 NOV 1951

Received from  
Chief Ship Surveyor:

SHIP'S NAME: *Taroona*

REPORT: *Syd* NO: *28061.*

Outstanding Conditions of Class: *Subject to (cracked)  
flange coupling of rudder head (E.W. 3+9)  
being specially examined at the next  
dry-docking.*

Endorsement of Class (B) (As before ~~to None~~)

Surveys due: *Special Survey (C) - 8.57*

Nature of Present Survey:

*Docking  
Special Survey.*

Special Features:

Items Outstanding: (If any for S.S. or A.S.)

Recommendation:

*Submitted docking date 9.57 and  
notation of SS Syd-9.57 be assigned  
subject as above.*

*9.57 Syd } subject  
SS Syd-9.57 }*

Endorsement of Class (B) amended

*Shell plates Nos 4 & 6 in 2nd & 3rd strakes  
below sheer (A.S.) set in  
Indents in keel and bottom  
shell plating (A.S.).*

© 2021

Lloyd's Register  
Foundation

012265-012272-0066