

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Tw. Sc. "TARDONA" Report Gls No. 55344**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due -


✕ 100A1 "with freeboard"

3 Dks

Cell DB 227' 433t DT/a 13' 48t DTf 20' 177t FPT 18t APT 26t

FK & EK 1 $\frac{1}{2}$ ", 8 EH (Coll EH to Weather Dk 7 EH to 2nd Dk), pt. cem., Lloyd's
A & CP
B & F 323'

Rudder electrically welded

Topsides—~~Special~~ Special Quality Steel

31.1.35



© 2021

Lloyd's Register
Foundation

012265012272-0081

20.

1802

1890-1891

THEY WERE BUILT FOR THE 1930S AND ARE NOT FIT FOR

© 2021

LOYD'S REGISTER
FOUNDATION

21387

1000

1820