

Received from Chief Ship Surveyor

18 JUN 1956

SHIP'S NAME "EDWARD JANSEN" REPORT Nwc. No. 133 15

GB

Outstanding Conditions of Class:

Subject to tunnel recess top beams, etc. and bulkhead stiffeners being specially examined and dealt with as necessary also to sternframe (E.W. & reinforced 2,54) and adjacent plating (s.s.) (E.W. 3,55) being specially examined, next drydocking, and to slightly set in shell plate F.5 (s.s.f.) being permanently repaired by next Special Survey.

Endorsement of Class (B) (As before ~~or None~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs (various causes) and to part of the deferred and Endorsement of Class (B) items as above:
O.F. conversion in accordance with approved plans and Rule requirements.

Recommendation:

SUBMITTED record of docking 4,56 be assigned, subject to sternframe (E.W. & reinforced 2,54) and adjacent shell plating (s.s.) (E.W. 3,55) being specially examined next drydocking, without other conditions but with Endorsement (B).

4,56Nwc. Subject
Without.

ENDORSEMENT OF CLASS (B).
Stem and stem plating, etc. set in.

INSERT IN R.B.


O.F. 4,56.

Side tanks in mchy space O.F.

FREEBOARD SURVEYORS TO NOTE this report.

Blk(new)

tc.
Noted
for
Header



7-6-56

Lloyd's Register
Foundation

012273-012278-0108