


TELEPHONE: 36873 (2 LINES).



Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

SS "Vic 82"

Hull, 23rd May, 1945.

In reply to the query contained in your letter of the 18th instant, we have to state that the reason for the fitting of steering chains 5/8" in diameter in "VIC 81" was due to the delay in receiving the 9/16" chains on order for this vessel and as 5/8" chains intended for another vessel had been delivered in good time, these chains were fitted in "VIC 81" to facilitate the vessel being put into service.

Plan of Sternframe & Rudder etc. is at present in the Freeboard Department.

We are, Dear Sir,
Yours faithfully,
The Surveyors,

Per: *[Signature]*

The Secretary,
WOKINGHAM.

Freeboard Dept states that plans returned to Hull on 22.5.45

© 2021
Lloyd's Register
Foundation

L.C.D.

Do

Handwritten scribbles and illegible text

Handwritten signature: R. He

Dear Sir,

Dear Sir,

Reference is made to the letter of the 14th inst.

in which you request that we should
be pleased to issue a letter of
reference for the purpose of
advising the Board of Directors
of the fact that you have
been appointed to the position
of Secretary of the Board
of Directors of the
Company.

Very truly yours,
R. He

28 Nov 22



© 2021

Lloyd's Register
Foundation

Gro