

"VIC 82"

F.E. Rpt. Hul.No.52897.

It is submitted before this case receives consideration the Surveyors be requested to state the reason for the reduction in the diameter of the steering chains from $\frac{5}{8}$ " as fitted in the sister vessel "VIC 81" to $\frac{2}{16}$ " in this vessel and to forward the approved plans of rudder, quadrant or tiller.

*See letter 16.5.45
& 26.5*

f.c.d
16.5.45 *CAH*



© 2021

Lloyd's Register
Foundation